LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

FILE NO. 912-C

INDIVIDUAL SEWAGE SYSTEM CONSTRUCTION — March 4, 1977

TYPE OF PERMIT — THIS PERMIT EXPIRES

Roger Johnson — Route #1, Adams 68301

ISSUED TO — ADDRESS

T9N; R5E; Sec. 3; Lot 7 I.T.

LEGAL DESCRIPTION

REMARKS: NON-TRANSFERABLE

PERMIT	INSPECTION FEE	OCCUPATION TAX	TOTAL
$ 30.00	$	$	$ 30.00
ACCOUNTING NO.	ACCOUNTING NO.	ACCOUNTING NO.	CODE
	110.16	148.14	6-2

RECEIPTED BY — DATE — AMOUNT

VALID RECEIPT ONLY IF RECEIPTED IN THIS SPACE

HEALTH
ISSUING OFFICER

THIS PERMIT IS ISSUED AS PROVIDED BY COUNTY RESOLUTION NO. 2832

FORM HD-40(73) REQUEST FOR SITE CLEARANCE FOR INDIVIDUAL SEWAGE DISPOSAL SYSTEM

City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502 (Phone: 475-6221)

FILE NO. 912-C

TO: Division of Environmental Health
Lincoln-Lancaster County Health Dept.

DATE: Sept 2-76

The undersigned hereby requests SITE CLEARANCE to construct an Individual Sewage Disposal System in conformance with appropriate resolution or ordinance, as described herein:

SEE ATTACHED

1. Legal description of property: Twp. 9N ; Range 5E ; Section 3
Block ____; Lot p 7 I.T. ; Addition ____
Street Address ____

2. Property Use: Residential ____ ☒ ; Commercial ____ ☐
No. of Bedrooms 3 . Describe: ____
Other Use ____ ☐
Describe: ____

3. Type of Individual Sewage Disposal System: Septic Tank ☒ ; Other ☐

4. Distance to public sewer: ____ ft.

ROGER JOHNSON
Signature of Applicant (Owner or Lessee)

RT 1 ADAMS NEBR. 68301
Address

(Do not write below this double line)

REVIEWING ACTION

1. Health Department: Date Rec'd. 9/2/76 . Date Frwd. 9/2/76 . ACTION: Approved ☒ Disapproved ☐ Signature: Jerrold C. Hood

2. Supt. Bldg. Insp.: Date Rec'd. 9-8-76 . Date Frwd. 9-8-76 . ACTION: Approved ☐ Disapproved ☒ Signature: Williamson

3. City or County Engineer: Date Rec'd. 9-7-76 . Date Frwd. 9-7-76 . ACTION: Approved ☐ Disapproved ☒ Signature: Henry Graff

REMARKS OR REASONS FOR DISAPPROVAL ____

White: Health Dept. Copy
Yellow: Engineers Copy
Pink: Bldg. Inspector's Copy

FORM HD- 43(73) SOIL ABSORPTION TEST DATA REPORT
(Annex to Application)
(Reference: City Ordinance No. 9150 and County Resolution No. 2832)

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502 (Phone 475-6221)

FILE NO. 912C

PROPERTY WHERE SOIL TESTED:
Location: Township 9; Range 5E
Section & ¼ Sect. _____
Property Dimensions: ____ ft. x ____ ft.
Area: _____ acres. (Attach sketch of property showing hole location).
Soil Type: Silty Clay [ ]; Silty Clay Loam [ ]; Sandy Loam [ ]
Silty Loam [ ]; Clay Loam [ ]; Sandy Clay [ ]

Owner: ROGER JOHNSON
Address RT 1 ADAMS NEBR. 68301

Dates of Tests: AUG 19-76 to AUG 20-76. Weather: Precip. ____ Temp. ____

PERCOLATION TEST DATA TABLE

a.	b.	c.	d.	e.	f.	g.	h.	i.	j.	k.	l.	m.	n.
		Pre-Saturation Period				Percolation Readings					Results		
		Start		End		Start			End				
Hole No.	Hole Depth (in.)	Date (Mo. Day)	Time (Hr. Min.)	Date (Mo. Day)	Time (Hr. Min.)	Date (Mo. Day)	Time (Hr. Min.)	Water Level (in.)	Time (Hr. Min.)	Water Level (in.)	Elapsed Time (Min.)	Water Level Drop (in.)	Percolation Rates (Min./inch)
1	30	AUG 19	02:00	AUG 20	3:00	AUG 20	4:55	16½	5:25	18½	30	2	
2	"	"	"	"	"	"	"	19⅝	"	21	"	1⅜	
3	"	"	"	"	"	"	"	22½	"	24¾	"	2¼	
4	"	"	"	"	"	"	"	19½	"	21½	"	2	
5	"	"	"	"	"	"	"	25	"	27	"	2	
6	"	"	"	"	"	"	"	25	"	27	"	2	

Sum of Percolation Rates _____
Average of Rates: _____
Mean of Rates: _____

Norm Beyhausen
Signature of Person Conducting Test

Address 3300 N 53
Phone: 466-5210

(Do not write below this line)

REVIEWING ACTION

REMARKS: _____

Approved Percolation Rate(s)
A. 15 min./inch
B. _____ min./inch
C. _____ min./inch

DATE: September 2, 1976

Jerrold C. Wood
Signature of Reviewing Official

FORM HD- 45(73) PLANS & SPECIFICATIONS, SEWAGE DISPOSAL SYSTEM

(Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502 (Phone: 475-6221)

FILE NO. 912-C

SPECIFICATIONS

DATE: Sept 2-76


A. BUILDING SEWER:
1. Material _____; Diameter ____ in.
2. Distance above basement floor ____in.; or below basement floor ____in.
3. Distance between dwelling and septic tank ____ft.
4. Number of clean-outs _____.
5. Distances To:
Well or Suction Line ____ft.;
Stream ____ft.; Pressure Line ____ft.;
Property Line ____ft.

B. SEPTIC TANK (Provide construction drawings.)
1. Material FIBER GLAS; No. of compartments 1.
2. Capacity 1000 gals.; Liquid depth ____in.
3. Factory Built: Yes ☒ (Company CORRA GLAS)
No ☐
4. Manholes: Over Inlet; diam. ____in.
Over Outlet; diam. ___in.
Below Grade _____in.
5. Inlet: Baffle ☐; or Tee ☐
6. Outlet: Baffle ☐; or Tee ☐
Depth of outlet below inlet ___in.
7. Depth of top of tank below finished grade ____in.
8. Distances To:
Well or Suction Line ____ft.;
Stream ____ft.; Pressure Line ____ft.;
Property Line ____ft.

C. DISTRICTION BOX
1. Material _____; No. available outlets _____.
2. Factory Built: Yes ☐, (Company _____) No ☐
3. Dimension: Length ____in.; Width ___in. Depth ____in.
4. Distance from Septic Tank ____ft.
5. Serial Distribution: Yes ☐, No ☐ (If yes, show detailed plans.)


D. ABSORPTION FIELD: (Provide drawings.)
1. Type: HALF ROUND
2. Lateral Lines: Depth below grade ___in. Number ____; Length of each line ___ft Total length of Laterals 143 ft.; Slope ____in/100 ft. Diameter of pipe ____ in.; Shape _____
Material: concrete ☐; fiber asbestos ☐; clay ☐; other _____
Distance between lateral lines ____ft.
3. Trench Dimensions: Depth ___in.; Width 48 in.
4. Filter Material: _____.
Depth of material from trench bottom _____in.
5. Distances To:
Well or Suction Line ____ft.;
Stream _____ft.; Pressure Line ____ft.
Property Line ____ft.
6. Percolation Rate: 15 minutes/inch

TYPICAL SKETCHES



ROGER JOHNSON
Signature of Applicant

Norm Berglund
Nov 9- 76




LANCASTER COUNTY, NEBRASKA

Survey of: irregular tracts in part of Lot 7, in

Section 3 T 9 N, R 5 E of 6th P.M.

Survey No. (To be assigned by County Surveyor)

Date Aug 24 1976 Weather



Field Notes:

Show descriptions of corners found and restored; distances chained; angles measured, if any; courses and bearings of irregular tracts surveyed; and ties taken to corners. Use reverse side if necessary.

Description of corners found

East ¼ corner found pin in paving

Southeast corner founf pim in paving

South ¼ corner found Brass cap

Center 1/16 corner East found ½" pipe

East 1/16 corner between 9 & 16 set spike midway and on line

½ pipe set at all lot corners