LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

2200 ST. MARYS
LINCOLN, NEBRASKA 68502

FILE NO. 1960-C

INDIVIDUAL SEWAGE SYSTEM CONSTRUCTION — TYPE OF PERMIT

September 3, 1983 — THIS PERMIT EXPIRES

Jerry Hutcheson %Paul Van Gillern — ISSUED TO

3308 N. Cotner 68507 — ADDRESS

T9N, R5E, SECTION 25 W½ of NE¼ — LEGAL DESCRIPTION

REMARKS: NONTRANSFERABLE New System

PERMIT	INSPECTION FEE	OCCUPATION TAX	TOTAL
$60.00	$	$	$60.00
ACCOUNTING NO.	ACCOUNTING NO.	ACCOUNTING NO.	CODE
	110.16	148.14	6-2

RECEIPTED BY	DATE	AMOUNT
EB	3/4/83	

VALID RECEIPT ONLY IF RECEIPTED IN THIS SPACE

HEALTH — ISSUING OFFICER

THIS PERMIT IS ISSUED AS PROVIDED BY COUNTY RESOLUTION NO. 2832

20109-0977

FORM 20103-0477
REQUEST FOR SITE CLEARANCE AND PERMIT
FOR INDIVIDUAL SEWAGE DISPOSAL SYSTEM
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 474-1541

A

FILING FEE: $ 60.00

FILE NO. 1960-C

DATE: 3-2-83

The undersigned hereby requests SITE CLEARANCE and PERMIT to construct an Individual Sewage Disposal System in conformance with appropriate resolution or ordinance, as described herein:

1. Legal description of property: Twp. 9N ; Range 5E ; Section 25 ; W½ OF NE¼
   Block _____ : Lot _____ : Addition _____
   Street Address Yankee Hill Road
2. Property Use: Residential ☒ ; Commercial ☐ Other Use ☐
   No. of Bedrooms 3 . Describe _____
3. Type of Individual Sewage Disposal System: Septic Tank ☐ ; Other ☒ Lagoon Must be Sealed
4. Distance to public sewer: _____ ft.

Terrell Hutcheson 489-2988
Signature of Applicant (Owner or Lessee)
c/o Paul Van Billiard
3308 N Cotner
Address
467-4792 68507

(Do not write below this double line)

1. Health Department: Date Rec'd. 3/2/83 . Date Frwd. 3/4/83 . ACTION: Approved ☒ Disapproved ☐ Signature: Jerrold C. Wood
2. Supt. Bldg. Insp.: or Village Clerk Date Rec'd. _____ . Date Frwd. 3-4-83 . ACTION: Approved ☒ Disapproved ☐ Signature: [signature]
3. City or County Engineer : Date Rec'd 3/4/83 . Date Frwd. 3/4/83 . ACTION: Approved ☒ Disapproved ☐ Signature: [signature]

REMARKS OR REASONS FOR DISAPPROVAL Approved for Foundation - 20+ac. Pumps

Site Visits:
Date: 5-10-83 by: [signature]
Date: _____ by: _____
Date: _____ by: _____

White: Health Dept. Copy
Yellow: Engineers Copy
Pink: Bldg. Inspector's Copy

INSTALLATION FINAL WRITTEN APPROVAL
Date: 5-13-83 By: Ron Maynard

FORM 20104-0477
PLANS & SPECIFICATIONS FOR SEWAGE DISPOSAL SYSTEM (Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 474-1541

D

DATE: 5/11/83

FILE NO. 1960

Bottom 11'X11' 48"x48" inside Dike Lagoon


SPECIFICATIONS AS BUILT

A. BUILDING SEWER:
1. Material PVC ; Diameter 4" in.
2. Distance above basement floor_____ in., or below basement floor____in.
3. Distance between dwelling and septic tank_____ft.
4. Number of clean-outs 2 .
5. Distances to:
Well or Suction Line_____ft.; Stream_____ft.; Pressure Line _____ft.; Property Line_____ft.

B. ~~SEPTIC TANK:~~
1. Material_____; No. of compartments_____.
2. Capacity_____gals.;
3. Factory Built: Yes ☐ No ☐
(Company_____)
4. Manholes: Over Inlet; diam._____in.
Over Outlet; diam._____in.
Riser Above ☐ Below ☐ Grade____in.
5. Inlet: Baffle ☐ ; or Tee ☐
6. Outlet: Baffle ☐ ; or Tee ☐
7. Depth of top of tank below finished grade_____in.
8. Distances to:
Well or Suction Line_____ft.; Stream_____ft.; Pressure Line _____ft.; Property Line_____ft.

C. ~~DISTRIBUTION BOX:~~
1. Material_____; Number - available outlets_____.
2. Factory Built: Yes ☐ No ☐
(Company_____)
3. Distance from Septic Tank_____ft.

D. ~~ABSORPTION FIELD:~~ (Provide as built drawings on back of this form)
1. Type: Half Rounds ☐ Perforated Pipe ☐
Diameter of Half Round_____ or Perforated Pipe_____.
Material: fiberglass ☐ ;plastic ☐ ; concrete ☐ ; other_____.
2. Lateral Lines:
Number___ ;Length of each line_____, _____,_____,_____,_____ft.;
Total length of laterals_____ft.;
Distance between lateral lines____ft.
3. Trench dimensions: Width_____ft.;
Slope_____in/100 ft.; Average Depth_____in.
4. Filter Material:_____
Depth of Material_____in.
5. Distances to:
Well or Suction Line_____ft.; Stream_____ft.; Pressure Line _____ft.; Property Line_____ft.



TYPICAL INDIVIDUAL SEWAGE SYSTEM DESIGN

004

Lincoln-Lancaster County Health Department

2200 St. Mary's Avenue, Lincoln, Nebraska 68502 Phone: 441-8022

REAL ESTATE TRANSFER/LOAN APPROVAL FORM

This form must be completed and returned to request a real estate transfer inspection.

MAKE CHECK PAYABLE TO: Lincoln-Lancaster County Health Department or LLCHD

☒ Enclosed is $150.00. Allow two weeks for processing. Incomplete information will delay processing.

☐ Evaluation of the Individual Water System ☒ Evaluation of the Sewage Disposal System

Legal Description of Property: Street Address 6205 W. YANKEE HILL RD, DENTON, NE 68339

Twp 9N Range 5E Section 25 1/4 NE 1/4 ____ Block ____ Lot 13 Addition ____

Directions to Property SW 56TH & DENTON RD Then 1/2 MILE WEST ON YANKEE HILL RD - 3 MILES EAST OF DENTON

Location of Well JUST off NW CORNER OF HOUSE Tap Location: Inside ☐ Outside ☒

Location of Sewage System LAGOON - A LITTLE SOUTH & EAST OF HOUSE Year Installed ____

	NAME	ADDRESS	PHONE
Present Owner:	TERRY HUTCHESON	6205 W. YANKEE HILL RD, DENTON, NE 68339	797-7445
~~Tenant~~/Buyer:	JOHN & GLORIA BAKER	1300 So. 112TH - LINCOLN, NE 68520	436-1934
Return to:	ROGER de BROWN, HOME R.E.	225 No. COTNER BLVD. LINCOLN, NE 68505-2341	436-3288

Signature of Applicant ⊗ John a Baker Address 1300 So. 112TH LINCOLN, NE 68520 Date 7/14/93

HEALTH DEPARTMENT USE ONLY

Date Received 7/23/93 Received $150.00 Check ☒ Cash ☐

PRELIMINARY STATUS--By Carroll Hood **DATE:** 7/27/93

WATER SYSTEM:	Approved	Disapproved	SEWAGE SYSTEM	Additional Site Visits
Construction	☒	☐	Approved ☐	Date 8/2/93 by J.C.H.
Bacteria	☒ 0 /ml	☐ ____ /ml	Provisional ☐	Date 9/2/93 by J.C.H.
Nitrate	☒ <0.1 ppm	☐ ____ ppm	Disapproved ☒	Date ___/___/___ by ____

Comments: LAGOON IS OVERFLOWING. NORTHEAST CORNER OF FENCE IS TOO SHORT WITH ADDED DIRT THERE. 8/2/93 LAGOON IS DOWN. J.C.H. More fence added 9/2/93 See Attached Letter ☐

FINAL STATUS

WATER SYSTEM: Approved: ☒ **SEWAGE DISPOSAL SYSTEM** Approved: ☒ Provisional Approval: ☐

Approved by Carroll C. Hood R.E.H.S. Date 9/2/93

Approval or disapproval is based on State and local standards for construction, location and water quality. Inspection is based on visible construction and operation at the time of inspection. Approval or provisional approval does not imply or express a guarantee of system operations.

054

AS BUILT DRAWING OF SYSTEM

DATE 5/11/83 INSTALLER Harlan L. Rechling

owner Terry Hutchison

