CITY OF LINCOLN NEBRASKA

DEPARTMENT OF LICENSES AND PERMITS

FILE NO. 95

INDIVIDUAL SEWAGE SYSTEM CONSTRUCTION
TYPE OF LICENSE OR PERMIT

October 1, 1969
THIS LICENSE OR PERMIT EXPIRES

Hub Hall by Larry L. Irwine
LICENSEE OR PERMITTEE

111 Piazza Terrace
ADDRESS

T 9N; R 7E; Sec. 22; Blk. 3; Lot 7; Clarendon Hills Addition, RR 8
NAME OF ESTABLISHMENT, IF ANY

ADDRESS

REMARKS: Non-Transferable

PERMIT	INSPECTION FEE	OCCUPATION TAX	LICENSE	TOTAL
$ 30.00	$	$	$	$ 30.00

ACCOUNTING NO.	ACCOUNTING NO.	ACCOUNTING NO.	CODE
1431-10.1535	110.16	148.14	6-2

SERIAL NO.	DATE	AMOUNT
15169	[illegible] 19	3000

VALID RECEIPT ONLY IF MACHINE RECEIPTED IN THIS SPACE

APPLICATION

THIS LICENSE OR PERMIT IS ISSUED SUBJECT TO REVOCATION AS PROVIDED BY LAW

FORM HD-32(67) APPLICATION FOR PERMIT
TO CONSTRUCT INDIVIDUAL SEWAGE
DISPOSAL SYSTEM
City Ordinance No. 9150

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502 (Phone: 432-7611)

FILE NO. 95

DATE: 21 MARCH 1969

TO: Director of Health
Lincoln-Lancaster County Health Dept.

The undersigned hereby applies for a permit to construct an Individual Sewage Disposal System in conformance with Lincoln City Ordinance No. 9150, as described in this application and the annexed forms attached hereto.

1. Legal description of property: Twp. 9N; Range 7E; Section 22;
Block 3; Lot #7; Addition CLARENDON HILLS
Street Address R.R. #8.

2. Property Use: Residential ☒; Commercial ☐
No. of Bed Rooms 3
Describe:

Other Use ☐
Describe:

3. Type of Individual Sewage Disposal System: Septic Tank ☒; Other ☐

4. Plans and Specifications of Proposed System. (See FORM HD-32a(67) PLANS & SPECIFICATIONS, SEWAGE DISPOSAL SYSTEM, attached hereto.)

5. Soil Absorption Properties. (See FORM HD-33(67) SOIL ABSORPTION TEST DATA REPORT, attached hereto.)

Hub Hall by Larry L. Irvine
Signature of Applicant (owner or lessee)

111 Piazza Terrace
Address

(Do not write below double line)

REVIEWING ACTION

1. Date Rec'd:
Filing Fee: $

2. Date Site Clearance

3. Site Visits:
Date: by:
Date: 5/28/69 by: L.C.H.
Date: by:

4. Date: Approved ☒; Disapproved ☐: 4/1/69
by: Jerrold C. Hood

5. BUREAU OF LICENSES & PERMITS
Date Notified:
Date Issued: Serial

6. INSTALLATION FINAL WRITTEN APPROVAL
Date: 5/28/69 by: Jerrold C. Hood

SEE EXTENSION FILE NO. 2008

FORM HD-32a(67) PLANS & SPECIFICATIONS
SEWAGE DISPOSAL SYSTEM
(Annex to Application)
Ordinance No. 9150

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502 (Phone: 432-7611)

FILE NO. 95

SPECIFICATIONS

DATE: 27 March 1969


A. BUILDING SEWER:
1. Material P.V.C; Diameter 4 in.
2. Distance above basement floor ___ in.; or below basement floor ___ in.
3. Distance between dwelling and septic tank 5 ft.
4. Number of clean-outs ___.
5. Distances To:
Well or Suction Line 50 ft.;
Stream ___ ft.; Pressure Line ___ ft.;
Property Line ___ ft.

B. SEPTIC TANK (Provide construction drawings.)
1. Material ~~CONCRETE~~ FIBERGLAS; No. of compartments ONE.
2. Capacity 1000 gals.; Liquid depth 47 in.
3. Factory Built: Yes [X] (Company ~~PRE CAST~~ CORRUGATED FIBERGLAS)
No [ ]
4. Manholes: Over Inlet; diam. 7 in.
Over Outlet; diam. ___ in.
Below Grade 12 in.
5. Inlet: Baffle [ ]; or Tee [ ]
6. Outlet: Baffle [ ]; or Tee [X]
Depth of outlet below inlet 1 in.
7. Depth of top of tank below finished grade 12 in.
8. Distances To:
Well or Suction Line 50 ft.;
Stream ___ ft.; Pressure Line ___ ft.;
Property Line ___ ft.

C. DISTRIBUTION BOX
1. Material CONCRETE No. available outlets 5.
2. Factory Built: Yes [X], (Company PreCast Step) No [ ]
3. Dimension: Length 18 in.; Width 14 in. Depth 4 in.
4. Distance from Septic Tank 4 ft.
5. Serial Distribution: Yes [ ], No [X]
(If yes, show detailed plans.)

D. ABSORPTION FIELD: (Provide drawings.)
1. Type: ~~CONCRETE~~ FIBERGLAS ~~CONCRETE~~ HALF MOON
2. Lateral Lines: Depth below grade 20 in.
Number 2; Length of each line 75 ft
Total length of Laterals 150 ft.;
Slope 10 in/100 ft. Diameter of pipe 6 in.; Shape ( )
Material: concrete [X]; fiberGLAS
asbestos [ ]; clay [ ]; other ___
Distance between lateral lines 15 ft.
3. Trench Dimensions: Depth 44 in.;
Width 24 in.
4. Filter Material: GRAVEL.
Depth of material from trench bottom 8 in.
5. Distances To:
Well or Suction Line 100 ft.;
Stream ___ ft.; Pressure Line ___ ft.
Property Line ___ ft.
6. Percolation Rate: ___ minutes/inch

TYPICAL SKETCHES




SEPTIC TANK

DISTRIBUTION BOX

TRENCH & LATERAL

Hubert Hall by Laraye Irvine
Signature of Applicant



RED ADDITION MADE AUGUST 21, 1970 BY ROGER BAILEY

008

Lincoln-Lancaster County Health Department

2200 St. Mary's Avenue, Lincoln, Nebraska 68502 Phone: 441-8022

REAL ESTATE TRANSFER/LOAN APPROVAL FORM

This form must be completed and returned to request a real estate transfer inspection.

MAKE CHECK PAYABLE TO: Lincoln-Lancaster County Health Department or LLCHD

☒ Enclosed is $150.00. Allow two weeks for processing. Incomplete information will delay processing.

☒ Evaluation of the Individual Water System ☒ Evaluation of the Sewage Disposal System

Legal Description of Property: Street Address 7320 Travis Drive, Lincoln, NE 68516

Twp 9N Range 7E Section 22 1/4 ___ 1/4 ___ Block 3 Lot 7 Addition Clarendon Hills 1st

Directions to Property _____

Location of Well _____ Tap Location: Inside ☐ Outside ☐

Location of Sewage System _____ Year Installed _____

	NAME	ADDRESS	PHONE
Present Owner:	Joseph & Nancy Delgado	7320 Travis Drive Lincoln, NE 68516	432-1972 (Nancy's Cellular)
Tenant/Buyer:			
Return to:	Lincoln Bank South Lincoln Bank South	4100 South 27th Street Lincoln, NE 68502	423-2361

Signature of Applicant By: Carol A Mott Address 4100 So. 27th St Lincoln, NE 68502 Date 10 /15 /93

HEALTH DEPARTMENT USE ONLY

Date Received 10 / 18 / 93 Received $150.00 Check ☒ no. #25438 Cash ☐

PRELIMINARY STATUS--By Jerrold Hood **DATE:** 10 / 28 / 93

WATER SYSTEM:	Approved	Disapproved	SEWAGE SYSTEM	Additional Site Visits
Construction	☒	☐	Approved ☒	Date ___/___/___ by ___
Bacteria	☒ 0 /ml	☐ ___ /ml	Provisional ☐	Date ___/___/___ by ___
Nitrate BOTH	☒ <0.1 ppm	☐ ___ ppm	Disapproved ☐	Date ___/___/___ by ___

Comments: _____

See Attached Letter ☐

FINAL STATUS

WATER SYSTEM: Approved: ☒ **SEWAGE DISPOSAL SYSTEM** Approved: ☒ Provisional Approval: ☐

Approved by Jerrold C. Hood R.E.H.S. Date 11 / 1 / 93

Approval or disapproval is based on State and local standards for construction, location and water quality. Inspection is based on visible construction and operation at the time of inspection. Approval or provisional approval does not imply or express a guarantee of system operations.

144

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

2200 St. Marys Avenue Phone (402) 471-7800 Lincoln, Nebraska 68502

REAL ESTATE TRANSFER / LOAN APPROVAL

This form must be completed and returned to request a real estate transfer inspection.

MAKE CHECKS PAYABLE TO: Lincoln-Lancaster County Health Department.

[XX] Evaluation of the Individual Water System Date: June 22, 1992

[XX] Evaluation of the Sewage Disposal System [XX] Enclosed is $150.00

Legal Description of Property: TWP. 9N ; RANGE 7E ; SECTION 22 ; BLOCK 3

LOT 7 ; ADDITION Clarendon 1st ; Street Address 7320 Travis Drive - Lincoln

Directions to Property Straight South of 70th Street and Hwy 2

Location of Well Front Yard Tap Location: Inside [ ] Outside [XX]

Location of Sewage System Back Yard Year Installed ____

	NAME	ADDRESS	PHONE
Present Owner:	Craig & D'Vee Buss	7320 Travis Drive	421-3776
Tenant/Buyer:	Joe and Nancy Delgado	9421 2nd Street - Cheney	421-8204
Return to:	Lynne Oswald-Home Real Est.	111 Piazza Terrace-Lincoln 68510	483-4663

NOTE: Allow two weeks for processing. Incomplete information will delay processing.

Signature of Applicant Nancy Delgado Address 9421 2nd St.-Cheney

==========

HEALTH DEPARTMENT USE ONLY

Date Received JUNE 23, 1992 Received $150.00 Check [X] Cash [ ]

PRELIMINARY STATUS--DATE JUNE 24, 1992

WATER SYSTEM:	Approved	Disapproved	SEWAGE SYSTEM:		SITE VISIT:
Construction	[ ]	[X]	Approved:	[ ]	Date 6/24/92 by J.C.H.
Bacteria	[X]	[ ]	Provisional:	[X]	Date 6/26/92 by J.C.H.
Nitrate <0.1 P.P.M.	[X]	[ ]	Disapproved:	[ ]	Date ____ by ____

Comments: DEPRESSION AROUND WELL. Corrected 6/26/92 J.C.H.
THE SOIL ON THIS LOT IS NOT CONDUCIVE TO GOOD SEPTIC SYSTEM OPERATION. IT IS A NATURAL THING AND HAS NOTHING TO DO WITH WORKMANSHIP OF THE SEPTIC INSTALLATION. LATERAL WAS ADDED ON 6/26/92 J.C.H. See Attached Letter [ ]

FINAL STATUS

	WATER SYSTEM:	SEWAGE DISPOSAL SYSTEM:	
	Approved: [X]	Approved: [ ]	Provisional Approval: [X]
APPROVED BY	Jerrold C. Hood R.E.H.S.	DATE	JUNE 30, 1992

Approval or disapproval is based on written standards for construction, location and water quality. Inspection is based on visible construction and operation at the time of inspection. Approval or provisional approval does not imply or express a guarantee of system operation. WELLS - Nebraska Safe Drinking Water Act,
- Standards for A Private Well in Nebraska

FG.4120 INDIVIDUAL SEWAGE SYSTEMS - County Resolution #2832