LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

3140 "N" STREET Lincoln, NE 68510-1514 (402) 441-8000

NON TRANSFERABLE

PERMIT

Permit
SEWAGE INSTALLATION

No. 96380145801

Issued 07/24/96
Expires 01/24/97
Revenue Code 18754

Establishment
DANA GREGORY
T12N R5E SEC 9

FEES: $150.00

TOTAL $150.00

Permittee
DANA GREGORY
10101 W LITTLE SALT RD
~~LINCOLN~~ NE
Valparaiso 68065

Issued By M. Jane Ford
Health Director

2393

THIS LICENSE OR PERMIT IS ISSUED SUBJECT TO REVOCATION AS PROVIDED BY LAW "POST IN A PROMINENT PLACE"

FORM 20103-0477
REQUEST FOR SITE CLEARANCE AND PERMIT
FOR INDIVIDUAL SEWAGE DISPOSAL SYSTEM
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
3140 N Street
Lincoln NE 68510
(402)-441-8022

A

FILING FEE: $ 150.00

FILE NO. _____

DATE: _____

The undersigned hereby requests SITE CLEARANCE and PERMIT to construct an Individual Sewage Disposal System in conformance with appropriate resolution or ordinance, as described herein:

1. Legal description of property: Twp. 12 N ; Range 5 E ; Section 9 ; W½-NW¼ of —
   Block _____ : Lot _____ : Addition _____
   Street Address 10101 W. Little Salt

2. Property Use: Residential ☑ ; Commercial ☐ Other Use ☐
   No. of Bedrooms 3 . Describe _____

3. Type of Individual Sewage Disposal System: Septic Tank ☐ ; Other ☐

4. Distance to public sewer: _____ ft.

Dana Gregory + Bill Ball
Signature of Applicant (Owner or Lessee)

10101 W. Little Salt
Address

(Do not write below this double line)

1. Health Department: Date Rec'd. 7/22/96. Date Frwd. 7/22/96. ACTION: Approved ☒ Disapproved ☐ Signature: Jerrold C. Rose

2. Supt. Bldg. Insp.: or Village Clerk Date Rec'd. 7/22/96. Date Frwd. 7/22/96. ACTION: Approved ☒ Disapproved ☐ Signature: TC

3. City or County Engineer: Date Rec'd. 7-22-96. Date Frwd. 7-22-96. ACTION: Approved ☐ Disapproved ☒ Signature: [signature]

REMARKS OR REASONS FOR DISAPPROVAL _____

Site Visits:
Date: 7-18-96 by: my next drawing
Date: 4-6-98 by: AB
Date: _____ by: _____

INSTALLATION FINAL WRITTEN APPROVAL
Date: 4-6-98 By: Jim Bare

White: Health Dept. Copy
Yellow: Engineers Copy
Pink: Bldg. Inspector's Copy

FORM 23-43

430-0861-0860 Jeff Dan

FORM 20105-0477
SOIL ABSORPTION TEST DATA REPORT
(Annex to Application)
(Reference: City Ordinance No. 9150 and County Resolution No. 2832)

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

B

MANN CUSTOMS

FILE NO. _____

PROPERTY WHERE SOIL TESTED:

Location: Township 12 ; Range 5 ; Section & ¼ Section W½-NW¼ of 9
Property Dimensions: _____ ft. x _____ ft. Area: 80 acres. (Attach Sheet C with sketch of property).
Soil Type: Silty Clay ☐ ; Silty Clay Loam ☑ ; Sandy Loam ☐ ; Silt Loam ☐ ; Clay Loam ☒ .
Dates of Tests: 2-24-96 to 2-25-96 . Weather: Precip. 0 Temp. 65°

Hole #6 had water remaining from pre-sat.

OWNER: Dana Gregory - Bill Bull
Address: 10101 W. Little Salt Rd.

PERCOLATION TEST DATA TABLE

a.	b.	c.	d.	e.	f.	g.	h.	i.	j.	k.	l.	m.	n.
		Pre-Saturation Period				Percolation Readings						Results	
		Start		End		Start			End				
Hold No.	Hole Depth (in.)	Date (Mo./ Day)	Time (Hr./ Min.)	Date (Mo./ Day)	Time (Hr./ Min.)	Date (Mo./ Day)	Time (Hr./ Min.)	Water Level (in.)	Time (Hr./ Day)	Water Level (in.)	Elapsed Time (Min.)	Water Level Drop (in.)	Percolation Rates (Min./in.)
1	36"	2-24	1:00 PM	2-25	5:15 PM	2-25	5:15 PM	6"	5:45 PM	5 1/4"	30 min	3/4"	40 MIN/IN
2	36"	2-24	1:00 PM	2-25	5:15 PM	2-25	5:15 PM	6"	5:45 PM	4 3/4"	30 min	1 1/4"	24 MIN/IN
3	36"	2-24	1:00 PM	2-25	5:15 PM	2-25	5:15 PM	6"	5:45 PM	4 3/4"	30 min	1 1/4"	24 MIN/IN
4	36"	2-24	1:00 PM	2-25	5:15 PM	2-25	5:15 PM	6"	5:45 PM	4 3/4"	30 min	1 1/4"	24 MIN/IN
5	36"	2-24	1:00 PM	2-25	5:15 PM	2-25	5:15 PM	6"	5:45 PM	5 1/2"	30 min	1/2"	60 MIN/IN
6	36"	2-24	1:00 PM	2-25	5:15 PM	2-25	5:15 PM	6"	5:45 PM	5 1/2"	30 min	1/2"	60 MIN/IN

Sum of Percolation Rates: _____
Average of Rates: _____
Mean of Rates: _____

Signature of Person Conducting Test

Address 2700 Dan Ave. Lincoln, Ne Phone 464-0638

(Do not write below this line)

REVIEWING ACTION

Remarks: _____
Soil Type (SCS): Sharpsburg Silty Clay Loam
Date: July 22, 1996

Approved Percolation Rate (a)
A. 60 min./inch
B. _____ min./inch
C. _____ min./inch

Gerald C. Hood
Signature of Reviewing Official

FORM 20104-0477
PLANS & SPECIFICATIONS FOR SEWAGE DISPOSAL SYSTEM (Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

D

DATE: _____

FILE NO. _____

10100 W. Little Salt


SPECIFICATIONS AS BUILT

A. BUILDING SEWER:
1. Material PVC ; Diameter 4 in.
2. Distance above basement floor _____ in., or below basement floor 20 in.
3. Distance between dwelling and septic tank 138 ft.
4. Number of clean-outs 2.
5. Distances to:
Well or Suction Line 100'+ ft.; Stream NA ft.; Pressure Line _____ ft.; Property Line 1/4 mi ft.

B. SEPTIC TANK:
1. Material Concrete ; No. of compartments one.
2. Capacity 1250 gals.;
3. Factory Built: Yes ☑ No ☐
(Company Pre-Cast)
4. Manholes: Over Inlet; diam. _____ in.
Over Outlet; diam. _____ in.
Riser Above ☐ Below ☐ Grade ☑ in.
5. Inlet: Baffle ☑ ; or Tee ☐
6. Outlet: Baffle ☑ ; or Tee ☐
7. Depth of top of tank below finished grade 6 in.
8. Distances to:
Well or Suction Line 100'+ ft.; Stream NA ft.; Pressure Line _____ ft.; Property Line 1/4mi ft.

C. DISTRIBUTION BOX:
1. Material Concrete ; Number available outlets six.
2. Factory Built: Yes ☑ No ☐
(Company Pre-Cast)
3. Distance from Septic Tank 8 ft.

D. ABSORPTION FIELD: (Provide as built drawings on back of this form)
1. Type: Half Rounds ☑ Perforated Pipe ☐
Diameter of Half Round 18" or Perforated Pipe _____.
Material: fiberglass ☐ ; plastic ☐ ; concrete ☑ ; other _____.
2. Lateral Lines:
Number 3 ; Length of each line 100, 100, 50, _____, _____ ft.;
Total length of laterals 250 ft.;
Distance between lateral lines 20+ ft.
3. Trench dimensions: Width 4 ft.;
Slope 2 in/100 ft.; Average Depth 36 in.
4. Filter Material: Road Gravel
Depth of Material 24 in.
5. Distances to:
Well or Suction Line 100'+ ft.; Stream NA ft.; Pressure Line _____ ft.; Property Line 1/4 mi ft.





TYPICAL INDIVIDUAL SEWAGE SYSTEM DESIGN

W

N

Drive


10' deep at house
46'
27'
65'
cleanout
1250 gal
8'
100' x 4'
50' x 4'
100' x 4'
2' diameter dist. box


T. 12 N.
SEWARD COUNTY
Little Salt Fk
Oak Creek
BRANCHED OAK STATE RECREATION AREA
5
6
4
7
8
9
18
17
16