LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

2200 ST. MARYS
LINCOLN, NEBRASKA 68502

FILE NO. 1815-C

INDIVIDUAL SEWAGE SYSTEM CONSTRUCTION — TYPE OF PERMIT

FEBRUARY 7, 1982 — THIS PERMIT EXPIRES

DON MULDER — ISSUED TO

4535 North 62th Lincoln NE — ADDRESS

T11N, R7E, Section 16, Lot 6 Irregular Tract Addition North West ¼ — LEGAL DESCRIPTION

REMARKS: NONTRANSFERABLE

PERMIT	INSPECTION FEE	OCCUPATION TAX	TOTAL
$ 60.00	$	$	$ 60.00
ACCOUNTING NO.	ACCOUNTING NO.	ACCOUNTING NO.	CODE
	110.16	148.14	6-2

RECEIPTED BY — DATE — AMOUNT

VALID RECEIPT ONLY IF RECEIPTED IN THIS SPACE

HEALTH

ISSUING OFFICER

THIS PERMIT IS ISSUED AS PROVIDED BY COUNTY RESOLUTION NO. 2832

20109-0977

FORM 20103-0477
REQUEST FOR SITE CLEARANCE AND PERMIT
FOR INDIVIDUAL SEWAGE DISPOSAL SYSTEM
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 474-1541

A

FILING FEE: $ 60.00

FILE NO. 1815-C

DATE: 7-15-81

The undersigned hereby requests SITE CLEARANCE and PERMIT to construct an Individual Sewage Disposal System in conformance with appropriate resolution or ordinance, as described herein:

1. Legal description of property: Twp. 11N ; Range 7E ; Section 16 ;
   Block _____ : ~~Lot 6 I.T.~~ : Addition North West ¼
   Street Address Now known as Lots 18 & 19 I.T.

2. Property Use: Residential ☐ ; Commercial ☒ Other Use ☐
   No. of Bedrooms _____. Describe Truck Terminal

3. Type of Individual Sewage Disposal System: Septic Tank ☒ ; Other ☐

4. Distance to public sewer: Miles ft.

Don Mulder
Signature of Applicant (Owner or Lessee)
Paul Mrs Auburn
4535 N 62 th
Address

(Do not write below this double line)

1. Health Department: Date Rec'd. 8/7/81. Date Frwd. 8/7/81. ACTION: Approved ☒ Disapproved ☐ Signature: Jerrold E. Hoot

2. Supt. Bldg. Insp.: or Village Clerk Date Rec'd. 8/7/81. Date Frwd. 8/7/81. ACTION: Approved ☒ Disapproved ☐ Signature:

3. City or County Engineer: Date Rec'd 8/7/81. Date Frwd. 8/7/81. ACTION: Approved ☐ Disapproved ☐ Signature: Larry Worrell Dep.

REMARKS OR REASONS FOR DISAPPROVAL _____

Site Visits:
Date: 12/15/81 by: J.C.H.
Date: _____ by: _____
Date: _____ by: _____

INSTALLATION FINAL WRITTEN APPROVAL
Date: _____ By: _____

White: Health Dept. Copy
Yellow: Engineers Copy
Pink: Bldg. Inspector's Copy

FORM 20105-0477
SOIL ABSORPTION TEST DATA REPORT
(Annex to Application)
(Reference: City Ordinance No. 9150 and County Resolution No. 2832)

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 474-1541.

B

FILE NO. _____

PROPERTY WHERE SOIL TESTED:

Location: Township 11N ; Range 7E ; Section & ¼ Section 16 North West ¼
Property Dimensions: 480E-W ft. x 490N-S ft. Area: 5.18 acres. (Attach Sheet C with sketch of property). LOT 6 E, Reg Tracts of Land

Soil Type: Silty Clay ☑; Silty Clay Loam ☐ ; Sandy Loam ☐ ; Silt Loam ☐ ; Clay Loam ☐

Dates of Tests: 4/5/80 to 4/7/80. Weather: Precip. 0 Temp 60.

This Test was conducted on North ½ of Property

OWNER: Don Mulder

Address: 1735 N 50 th
Lincoln, Ne. 68504

PERCOLATION TEST DATA TABLE

a.	b.	c.	d.	e.	f.	g.	h.	i.	j.	k.	l.	m.	n.
		Pre-Saturation Period				Percolation Readings						Results	
		Start		End		Start			End				
Hold No.	Hole Depth (in.)	Date (Mo./ Day)	Time (Hr./ Min.)	Date (Mo./ Day)	Time (Hr./ Min.)	Date (Mo./ Day)	Time (Hr./ Min.)	Water Level (in.)	Time (Hr./ Day)	Water Level (in.)	Elapsed Time (Min.)	Water Level Drop (in.)	Percolation Rates (Min./in.)
1	24	4/5	9:45	4/7	6:45	4/7	6:45	8	12:45	6 ¼	60	1 ¾	60 / 1 ¾
2	1	1	A.M	1	A.M	1	A.M	1	P.M	6 ⅜	1	1 ⅛	1 / 1 ⅛
3	1	1	1	1	1	1	1	1	1	6 ⅝	1	1 ⅜	1 / 1 ⅜
4	1	1	1	1	1	1	1	1	1	6 ⅞	1	1 ⅛	1 / 1 ⅛
5	1	1	1	1	1	1	1	1	1	6 ½	1	1 ½	1 / 1 ½
6	1	1	1	1	1	1	1	1	1	6 ⅛	1	1 ⅞	1 / 1 ⅞
7	1	1	1	1	1	1	1	1	1	5 ⅛	1	2 ⅛	1 / 2 ⅛
8	1	1	1	1	1	1	1	1	1	6	1	2	1 / 2

Paul von Gillern
Signature of Person Conducting Test

Address 3308 N Cotner Phone 467-4792

Sum of Percolation Rates: 13
Average of Rates: 1.625
Mean of Rates: 37

(Do not write below this line)

REVIEWING ACTION

Remarks: _____

Soil Type (SCS): Sharpsburg Silty Clay Loam

Date: April 9, 1980

Approved Percolation Rate (a)
A. 37 min./inch
B. _____ min./inch
C. _____ min./inch

Jerrold C. Hood
Signature of Reviewing Official

FORM 20102-0477
PRELIMINARY PLANS & SPECIFICATIONS FOR SEWAGE DISPOSAL SYSTEM (Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 474-1541

C

Sketch of property showing Percolation Test hole locations, well, residence, direction and property line.

FILE NO._____

Indicate on sketch if residence and well are exisiting or proposed.

REVIEWING ACTION

Remarks:_____

Date: August 7, 1981

Minimum Design Requirement
1. Capacity of Septic Tank 1000 gals.
2. Total Length of Laterals_____ft.
3. With a Trench Width of_____in.
4. Total Area of Lateral needed 112.5 sq.ft.

Jerrold C. Hood
Signature of Reviewing Official



MULDER TRUCKING

Lincoln, Nebraska

Phone

402 - 464-9189

Trucking Specialists

August 6, 1981

REC'D AUG 7 1981

The diagram that you asked for is on the blueprints that are on file with the City Building Permit Bureau.

LARRY CHILESE ARCHITECTS INC

Lancaster Health
Att: Nate Hartman
3140 N
Lincoln NE.

March 18, 2008

Re: 11850 No. 56th St. BP0800454

Dear Nate,

Pursuant to our phone conversation I am confirming the proposed 70x70 addition to the Auto Repair facility is free of any floor drains-sump pits, restrooms or any device which will add an additional load on the existing septic system.

The original building has existing restrooms, there are no provisions to expand, alter and add additional restrooms, sinks or drains.

For the firm

Larry Chilese NE: A-1581