FORM HD-41(73) APPLICATION FOR PERMIT TO ALTER, EXTEND OR REPAIR INDIVIDUAL SEWAGE DISPOSAL SYSTEM

City Ordinance No. 9150 [X]
County Resolution No. 2832 [ ]

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Ave.
Lincoln, Nebraska 68502 (Phone: 475-6221)

FILE NO._____

TO: Division of Environmental Health
Lincoln-Lancaster County Health Dept.

DATE: April 19, 1974

The undersigned hereby applies for a permit to ALTER [X], EXTEND [ ], or REPAIR [ ] an existing Individual Sewage Disposal System, in conformance with appropriate Ordinance or Resolution, as described in this application and drawings attached hereto.

1. Legal description of property: Twp. 11N; Range 6E; Section 30;
Block_____; Lot_____; Addition_____
Street Address Route 5

2. Property Use: Residential_____ [X]; Commercial_____ [ ]
No. Bedrooms 3 Describe_____
Other Use [ ]
Describe_____

3. Type of existing Individual Sewage Disposal System: Septic Tank [X]; Other [ ]

4. Description of proposed alteration, extension or repair: Install distribution box and install 108 ft. of concrete laterals and gravel

5. Work to be done by: Owner [X]; or Contractor [ ], _____
Contractor's Name

6. Estimated cost of project:

a. Materials	$ 197	62
b. Labor	$	
c. Other	$	
TOTAL	$ 197	62

Frank R. Dinsberger
Signature of Applicant (owner or lessee)

Route 5 Lincoln, Nebr.
Address

(Do not write below this line)

REVIEWING ACTION

1. Date Rec'd:_____
Filing Fee: $_____

2. Site Visits:
Date:_____ by:_____
Date:_____ by:_____
Date:_____ by:_____

3. Date: Approved [X]; Disapproved [ ]
by: Jerrold E. Hood

4. INSTALLATION FINAL WRITTEN APPROVAL
Date:_____ by:_____

FORM HD- 45(73) PLANS & SPECIFICATIONS
SEWAGE DISPOSAL SYSTEM

(Annex to Application)
City Ordinance No. 9150 ☒
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502 (Phone: 475-6221)

FILE NO. _____

T11N R6E Sec 29 NE 1/4

SPECIFICATIONS

DATE: 5-1-74


A. BUILDING SEWER: unknown
1. Material _____; Diameter ____ in.
2. Distance above basement floor ____in.; or below basement floor ____in.
3. Distance between dwelling and septic tank ____ft.
4. Number of clean-outs _____.
5. Distances To:
Well or Suction Line ____ft.;
Stream ____ft.; Pressure Line ____ft.;
Property Line ____ft.

B. SEPTIC TANK (Provide construction drawings.) unknown
1. Material _____; No. of compartments _____.
2. Capacity _____gals.; Liquid depth ____in.
3. Factory Built: Yes ☐ (Company _____)
No ☐
4. Manholes: Over Inlet; diam. ____in.
Over Outlet; diam. ___in.
Below Grade _____in.
5. Inlet: Baffle ☐; or Tee ☐
6. Outlet: Baffle ☐; or Tee ☐
Depth of outlet below inlet ___in.
7. Depth of top of tank below finished grade ____in.
8. Distances To:
Well or Suction Line ____ft.;
Stream ____ft.; Pressure Line ____ft.;
Property Line ____ft.


C. DISTRIBUTION BOX
1. Material Concrete; No. available outlets 6.
2. Factory Built: Yes ☒, (Company Ice Cast) No ☐
3. Dimension: Length ____in.; Width ___in. Depth ____in.
4. Distance from Septic Tank ____ft.
5. Serial Distribution: Yes ☐, No ☐ (If yes, show detailed plans.)

D. ABSORPTION FIELD: (Provide drawings.)
1. Type: 12" half moon
2. Lateral Lines: Depth below grade __in. Number 3; Length of each line 39ft Total length of Laterals 117 ft.; Slope ____in/100 ft. Diameter of pipe ____ in.; Shape ____
Material: concrete ☒; fiber asbestos ☐; clay ☐; other _____
Distance between lateral lines ____ft.
3. Trench Dimensions: Depth 48 in.; Width 24 in.
4. Filter Material: gravel.
Depth of material from trench bottom _____in.
5. Distances To:
Well or Suction Line ____ft.;
Stream _____ft.; Pressure Line ____ft.
Property Line ____ft.
6. Percolation Rate: _____minutes/inch

TYPICAL SKETCHES



FRANK DENSBERGER
Signature of Applicant


unknown distance
to septic tank
Tank
House
39'
39'
39'
Lateral is deeper than 5', but soil was to be removed from top to lower depth.

INTER-DEPARTMENT COMMUNICATION

TO **Charles Seale**

DEPARTMENT **Inspections**

ATTENTION

CARBONS TO

DATE **April 17, 1974**

FROM **Jerrold C. Hood, R. S.**

DEPARTMENT **Health**

SUBJECT **Frank Densberger Property**

We have been approached by Mr. Frank Densberger in regards to a new house to be built on his property in the NE 1/4 of Section 30, T11N, R6E. Mr. Densberger desires to utilize an existing septic system on his property to serve this house. We have agreed to allow him to use this pre-existing septic system but have required him to make certain corrections to this existing system in order to make it comply with Section 24.38 of the Lincoln Municipal Code within 30 days of todays date. An entire new system will not be required.

If you have any questions, please contact us.

Very truly yours,

Jerrold C. Hood, R. S., Chief
Section of General Sanitation
Division of Environmental Health

JCH:ch

Lincoln-Lancaster County Health Department

3140 "N" Street, Lincoln, Nebraska 68510 Phone: 441-8022

REAL ESTATE TRANSFER/LOAN APPROVAL FORM

FOR PROPERTY IN **LANCASTER COUNTY** ONLY

This form must be completed and returned with payment to request a real estate transfer inspection.

MAKE CHECK PAYABLE TO: "Lincoln-Lancaster County Health Department" or "LLCHD"

☐ Enclosed is $150.00. Allow two weeks for processing. Incomplete information will delay processing.

Legal Description of Property: Street Address 8205 NW 40th Lincoln Ne.
Twp 11 Range 6 Section 30 1/4 NE 1/4 Block ___ Lot 17 Addition ___
Directions to Property 1 mile North of Hwy 34 on NW 40th West side of Road.

Location of Well North of Large Machine Shed. Tap Location: Inside ☐ Outside ☑
Location of Sewage System South of house & North of South drive. Year Installed ___

	NAME	ADDRESS	PHONE
Present Owner:	Frank Densberger	84 Chickasaw Mountain Home ARK 72653	870-424-4934
Tenant/Buyer:			
Return to:	Capitol Title: ATTN Lila FAX 434-3736	4645 Normal Blvd Suite 150 PO Box 6577 Lincoln Ne. 68506	

Signature of Applicant Thomas H Green Address 4731 So 58th St Lincoln, Ne. 68516 Date 12/21/99

HEALTH DEPARTMENT USE ONLY

RECEIVED
Date 12/22/99
Initials ss
Amount 150.00
Check No. 4192

DATA ENTRY
Date ___/___/___
Case No. ___
Initials ___

PRELIMINARY STATUS--By Ron Marquart **DATE:** 12/23/99

WATER SYSTEM:	Approved	Disapproved
Construction	☒	☐
Bacteria	☒ 0 /ml	☐ ___ /ml
Nitrate	☒ 6.3 ppm	☐ ___ ppm

SEWAGE SYSTEM
Approved ☐
Provisional ☒
Disapproved ☐

Additional Site Visits
Date ___/___/___ by ___
Date ___/___/___ by ___
Date ___/___/___ by ___

Comments: Installation of the original septic system predates regulations. No permit or record of inspection are on file. This is a provisional approval. One hundred and twenty feet of drainfield lateral were installed to add to this system in 1974. There was no visible malfunction at the time of inspection. Recommend checking to see if septic tank needs pumping. ☐ See Attached Letter

FINAL STATUS

WATER SYSTEM: Approved ☒ **SEWAGE DISPOSAL SYSTEM:** Approved ☐ Provisional Approval ☒

Approved by Ron Marquart RS Date 12/29/99

Approval or disapproval is based on State and local standards for construction, location and water quality. Inspection is based on visible construction and operation at the time of inspection. Approval or provisional approval does not imply or express a guarantee of system operations.

White - Applicant after approval Yellow - Enviro

Revised/Reprint: 10-95

8205 NW 40th P14291-2 Pi Base P12403-45