LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

2200 St. Marys Ave Lincoln, NE 68502-3785 (402) 441-8000

NON TRANSFERABLE

P E R M I T

Permit
SEWAGE INSTALLATION

No. 93380100701

Issued 06/09/93
Expires 12/09/93
Revenue Code 18754

Establishment
DONALD MOELLER
T10N R7E SEC 14
LOT 72

FEES: $150.00

TOTAL $150.00

Permittee
DONALD MOELLER
3101 N 58 ST
LINCOLN NE 68507

Issued By M. Jane Ford
Health Director

THIS LICENSE OR PERMIT IS ISSUED SUBJECT TO REVOCATION AS PROVIDED BY LAW
"POST IN A PROMINENT PLACE"

FORM 20103-0477
REQUEST FOR SITE CLEARANCE AND PERMIT
FOR INDIVIDUAL SEWAGE DISPOSAL SYSTEM
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

A

FILING FEE: $ 150.00

FILE NO. _____

DATE: _____

The undersigned hereby requests SITE CLEARANCE and PERMIT to construct an Individual Sewage Disposal System in conformance with appropriate resolution or ordinance, as described herein:

1. Legal description of property: Twp. 10N ; Range 7E ; Section 14 ;
   Block _____ : Lot 72 I.T. : Addition _____
   Street Address 2501 No. 98th

2. Property Use: Residential ☑ ; Commercial ☐ Other Use ☐
   No. of Bedrooms 3 . Describe _____

3. Type of Individual Sewage Disposal System: Septic Tank ☑ ; Other ☐

4. Distance to public sewer: N.A ft.

Donald A Mode
Signature of Applicant (Owner or Lessee)

3101 N. 58 Lincoln 68507
Address

(Do not write below this double line)

1. Health Department: Date Rec'd. 6/4/93 . Date Frwd. 6/7/93 . ACTION: Approved ☑ Disapproved ☐ Signature: Jerrold C. Hood
2. Supt. Bldg. Insp.: or Village Clerk Date Rec'd. 6/7/93 . Date Frwd. 6/7/93 . ACTION: Approved ☑ Disapproved ☐ Signature: Harry Spain
3. City or County Engineer : Date Rec'd. 6-7-93 . Date Frwd. 6-7-93 . ACTION: Approved ☑ Disapproved ☐ Signature: R D Wilkins

REMARKS OR REASONS FOR DISAPPROVAL _____

Site Visits:
Date: 10-14-93 by: _____
Date: _____ by: _____
Date: _____ by: _____

White: Health Dept. Copy
Yellow: Engineers Copy
Pink: Bldg. Inspector's Copy

INSTALLATION FINAL WRITTEN APPROVAL
Date: 10-18-93 By: Ron Wagner

FORM 23-43

FORM 20105-0477
SOIL ABSORPTION TEST DATA REPORT
(Annex to Application)
(Reference: City Ordinance No. 9150 and County Resolution No. 2832)

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

B

FILE NO. _____

PROPERTY WHERE SOIL TESTED:

Location: Township 10 ; Range 7 ; Section & ¼ Section 14 .
Property Dimensions: _____ ft. x _____ ft. Area: 5+ acres. (Attach Sheet C with sketch of property).
Soil Type: Silty Clay ☐ ; Silty Clay Loam ☑ ; Sandy Loam ☐ ; Silt Loam ☐ ; Clay Loam ☐ .
Dates of Tests: 6/2/93 to 6/3/93 . Weather: Precip. Wet Temp. 60° .
OWNER: Donald A Moeller
Address: 3101 N. 58th Lincoln 68507

PERCOLATION TEST DATA TABLE

a.	b.	c.	d.	e.	f.	g.	h.	i.	j.	k.	l.	m.	n.
		Pre-Saturation Period				Percolation Readings						Results	
		Start		End		Start			End				
Hold No.	Hole Depth (in.)	Date (Mo./Day)	Time (Hr./Min.)	Date (Mo./Day)	Time (Hr./Min.)	Date (Mo./Day)	Time (Hr./Min.)	Water Level (in.)	Time (Hr./Day)	Water Level (in.)	Elapsed Time (Min.)	Water Level Drop (in.)	Percolation Rates (Min./in.)
1	30"	6/2/93	10:00	6/3/93	10:00	6/3/93	12:00	6	12:30		30	3/4	
2	"											1	
3	"											1 1/2	
4	"											1 1/4	
5	"											1 3/4	
6	"											1	

John Stuhmyer
Signature of Person Conducting Test

Sum of Percolation Rates: _____
Average of Rates: _____
Mean of Rates: _____

Address _____ Phone _____

(Do not write below this line)

REVIEWING ACTION

Remarks: _____
Soil Type (SCS): Sharpsburg Silty Clay Loam
Date: June 4, 1993

Approved Percolation Rate (a)
A. 25 min./inch
B. _____ min./inch
C. _____ min./inch

Jerrold C. Hood
Signature of Reviewing Official

FORM 20104-0477
PLANS & SPECIFICATIONS FOR SEWAGE DISPOSAL SYSTEM (Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

D

DATE: 10/93 Don Mueller

FILE NO. _____


SPECIFICATIONS AS BUILT

A. BUILDING SEWER:
1. Material PVC; Diameter 4 in.
2. Distance above basement floor _____ in., or below basement floor 20 in.
3. Distance between dwelling and septic tank _____ ft.
4. Number of clean-outs two.
5. Distances to:
Well or Suction Line 100' + ft.; Stream _____ ft.; Pressure Line _____ ft.; Property Line _____ ft.

B. SEPTIC TANK:
1. Material concrete; No. of compartments 1.
2. Capacity 1000 gal gals.;
3. Factory Built: Yes ☑ No ☐
(Company Pre-Cast)
4. Manholes: Over Inlet; diam. _____ in.
Over Outlet; diam. _____ in.
Riser Above ☐ Below ☐ Grade ____ in.
5. Inlet: Baffle ☑; or Tee ☐
6. Outlet: Baffle ☑; or Tee ☐
7. Depth of top of tank below finished grade 8 in.
8. Distances to:
Well or Suction Line 100' + ft.; Stream _____ ft.; Pressure Line _____ ft.; Property Line _____ ft.

C. DISTRIBUTION BOX:
1. Material concrete; Number - available outlets _____.
2. Factory Built: Yes ☑ No ☐
(Company Pre-Cast)
3. Distance from Septic Tank _____ ft.

D. ABSORPTION FIELD: (Provide as built drawings on back of this form)
1. Type: Half Rounds ☑ Perforated Pipe ☐
Diameter of Half Round _____ or Perforated Pipe _____.
Material: fiberglass ☐; plastic ☐; concrete ☑; other _____.
2. Lateral Lines:
Number 2; Length of each line 100', _____, _____, _____, _____ ft.;
Total length of laterals 200 ft.;
Distance between lateral lines ____ ft.
3. Trench dimensions: Width 4 ft.;
Slope 2 in/100 ft.; Average Depth _____ in.
4. Filter Material: Gravel
Depth of Material 10" in.
5. Distances to:
Well or Suction Line _____ ft.; Stream _____ ft.; Pressure Line _____ ft.; Property Line _____ ft.



TYPICAL INDIVIDUAL SEWAGE SYSTEM DESIGN

AS BUILT DRAWING OF SYSTEM

DATE 10/93 INSTALLER Strohmyer

