LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

Division of Environmental Health
2200 St. Marys Ave Lincoln, NE 68502 (402) 471-8000

NON TRANSFERABLE

PERMIT
SEWAGE INSTALLATION

No. 90380011801

Issued 05/02/90
Expires 11/02/90

ESTABLISHMENT
DONALD KINLEY
T11N R5E SEC 9 QTR SE
N 1/2 OF SE 1/4

FEES: Permit 018754 $150.00

Total $150.00

PERMITTEE
DONALD KINLEY
6008 ROBIN RD
LINCOLN NE 68516

Issued By COUNTY HEALTH

VALID RECEIPT ONLY IF RECEIPTED IN THIS SPACE

DATE AMOUNT

PAID

THIS LICENSE OR PERMIT IS ISSUED SUBJECT TO REVOCATION AS PROVIDED BY LAW

9038 00118

FORM 20103-0477
REQUEST FOR SITE CLEARANCE AND PERMIT
FOR INDIVIDUAL SEWAGE DISPOSAL SYSTEM
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

A

FILING FEE: $ 150.00

FILE NO. _____

DATE: _____

The undersigned hereby requests SITE CLEARANCE and PERMIT to construct an Individual Sewage Disposal System in conformance with appropriate resolution or ordinance, as described herein:

1. Legal description of property: Twp. 11N ; Range 5E ; Section 9 SE 1/4 N 1/2 of
   Block _____ : Lot _____ : Addition _____
   Street Address Lancaster County Nebraska (See attached)
2. Property Use: Residential ☒ ; Commercial ☐ Other Use ☐
   No. of Bedrooms 3 . Describe _____
3. Type of Individual Sewage Disposal System: Septic Tank ☒ ; Other ☐
4. Distance to public sewer: N/A ft.

Donald D Kinley
Signature of Applicant (Owner or Lessee)

6008 Robin Rd, Lincoln Ne 68516
Address

(Do not write below this double line)

1. Health Department: Date Rec'd. 4/13/90. Date Frwd. 5/14/90. ACTION: Approved ☒ Disapproved ☐ Signature: Errold C. Hood
2. Supt. Bldg. Insp.: or Village Clerk: Date Rec'd. 5-4-90. Date Frwd. 5-4-90. ACTION: Approved ☒ Disapproved ☐ Signature: Paul Boesen
3. City or County Engineer: Date Rec'd. _____. Date Frwd. 05/04/90. ACTION: Approved ☒ Disapproved ☐ Signature: Dwight Thompson

REMARKS OR REASONS FOR DISAPPROVAL _____

Site Visits:
Date: 10-18-90 by: rms need fence drawing - must be sealed
Date: 3-18-91 by: rms no fence
Date: 2-10-92 by: rms holding 30 ft with

White: Health Dept. Copy
Yellow: Engineers Copy
Pink: Bldg. Inspector's Copy

INSTALLATION FINAL WRITTEN APPROVAL
Date: 2-10-92 By: Ron Magenau

FORM 23-43

FORM 20105-0477
SOIL ABSORPTION TEST DATA REPORT
(Annex to Application)
(Reference: City Ordinance No. 9150 and County Resolution No. 2832)

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

B

FILE NO. _____

PROPERTY WHERE SOIL TESTED:

Location: Township 11 ; Range 5E ; Section & ¼ Section N½ of SE¼
Property Dimensions: _____ ft. x _____ ft. Area: 58.88 acres. (Attach Sheet C with sketch of property).
Soil Type: Silty Clay ☐ ; Silty Clay Loam ☒ ; Sandy Loam ☐ ; Silt Loam ☐ ; Clay Loam ☐ .
Dates of Tests: 3/20/90 to 3/21/90 . Weather: Precip. 0 Temp. 70° .

OWNER: Donald D Kinley
Address: 6008 Robin Rd Lincoln Ne 68516

PERCOLATION TEST DATA TABLE

a.	b.	c.	d.	e.	f.	g.	h.	i.	j.	k.	l.	m.	n.
		Pre-Saturation Period				Percolation Readings						Results	
		Start		End		Start			End				
Hold No.	Hole Depth (in.)	Date (Mo./ Day)	Time (Hr./ Min.)	Date (Mo./ Day)	Time (Hr./ Min.)	Date (Mo./ Day)	Time (Hr./ Min.)	Water Level (in.)	Time (Hr./ Day)	Water Level (in.)	Elapsed Time (Min.)	Water Level Drop (in.)	Percolation Rates (Min./in.)
1	3'	3/20/90	10:00am	3-20-90	4 Pm	3/21/90	2:33	22 5/8	3:04	23 3/8	31	6/8	41.33
2	3'	/	/	/	/	/	2:33	24 1/8	3:04	25 3/8	31	1 2/8	24.80
3	3'	/	/	/	/	/	2:34	22 1/8	3:05	22 3/4	31	5/8	49.60
4	3'	/	/	/	/	/	2:35	24	3:05	24 5/8	30	5/8	48.00
5	3'	/	/	/	/	/	2:35	23 1/4	3:06	24	31	3/4	41.33
6	3'	/	/	/	/	/	2:36	25 1/8	3:06	26 1/4	30	1 1/8	26.67

Sum of Percolation Rates: 231.73
Average of Rates: 38.62
Mean of Rates: 37.20

Donald D Kinley
Signature of Person Conducting Test

W- 434-4655

Address 6008 Robin Rd Phone 423-7740

(Do not write below this line)

REVIEWING ACTION

Remarks: _____
Soil Type (SCS): Sharpsburg + Judson in area
Date: April 13, 1990

Approved Percolation Rate (a)
A. 34 min./inch
B. _____ min./inch
C. _____ min./inch

Jerrold C Kool
Signature of Reviewing Official

FORM 20102-0477
PRELIMINARY PLANS & SPECIFICATIONS FOR SEWAGE DISPOSAL SYSTEM (Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☒


LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

C

Sketch of property showing Percolation Test hole locations, well, residence, direction and property line.

FILE NO. _____

Indicate on sketch if residence and well are exisiting or proposed.



REVIEWING ACTION

Remarks: _____

Date: April 13, 1990.

Minimum Design Requirement
1. Capacity of Septic Tank 1000 gals.
2. Total Length of Laterals _____ ft.
3. With a Trench Width of _____ in.
4. Total Area of Lateral needed 798 sq.ft.

Jerrold C. Hoad
Signature of Reviewing Official

FORM 20104-0477
PLANS & SPECIFICATIONS FOR SEWAGE DISPOSAL SYSTEM (Annex to Application)
City Ordinance No. 9150 ☐
County Resolution No. 2832 ☐

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT
Division of Environmental Health
2200 St. Marys Avenue
Lincoln, Nebraska 68502
Phone: 471-7800

D

DATE: 10-18

FILE NO. _____

Don Kinley


SPECIFICATIONS AS BUILT

A. BUILDING SEWER:
1. Material PVC ; Diameter 4 in.
2. Distance above basement floor _____ in., or below basement floor 10 in.
3. Distance between dwelling and ~~septic~~ Lagoon tank 225 ft.
4. Number of clean-outs 3 .
5. Distances to:
Well or Suction Line > 100 ft.; Stream > 100 ft.; Pressure Line N/A ft.; Property Line > 50 ft.


B. SEPTIC TANK:
1. Material _____; No. of compartments _____.
2. Capacity _____ gals.;
3. Factory Built: Yes ☐ No ☐
(Company _____)
4. Manholes: Over Inlet; diam. _____ in.
Over Outlet; diam. _____ in.
Riser Above ☐ Below ☐ Grade ____ in.
5. Inlet: Baffle ☐ ; or Tee ☐
6. Outlet: Baffle ☐ ; or Tee ☐
7. Depth of top of tank below finished grade _____ in.
8. Distances to:
Well or Suction Line _____ ft.; Stream _____ ft.; Pressure Line _____ ft.; Property Line _____ ft.

C. DISTRIBUTION BOX:
1. Material _____; Number - available outlets _____.
2. Factory Built: Yes ☐ No ☐
(Company _____)
3. Distance from Septic Tank _____ ft.

D. ABSORPTION FIELD: (Provide as built drawings on back of this form)
1. Type: Half Rounds ☐ Perforated Pipe ☐
Diameter of Half Round _____ or Perforated Pipe _____.
Material: fiberglass ☐ ; plastic ☐ ; concrete ☐ ; other _____.
2. Lateral Lines:
Number ___ ; Length of each line _____, _____, _____, _____, _____ ft.;
Total length of laterals _____ ft.;
Distance between lateral lines ____ ft.
3. Trench dimensions: Width _____ ft.; Slope _____ in/100 ft.; Average Depth _____ in.
4. Filter Material: _____
Depth of Material _____ in.
5. Distances to:
Well or Suction Line _____ ft.; Stream _____ ft.; Pressure Line _____ ft.; Property Line _____ ft.



TYPICAL INDIVIDUAL SEWAGE SYSTEM DESIGN


N
o well
NW
98th
65'
26'
75'
80'


SURVEY RECORD

LANCASTER COUNTY, NEBRASKA

Survey of SE¼ Section 9 T. 11 N., R. 5 E. of 6th P.M.

County Survey No.

Date JAN. 4 19 92 Weather CLOUDY, COOL



ROADWAY EASEMENT

A 30-FT. WIDE ROADWAY ACCESS EASEMENT DESCRIBED AS FOLLOWS: THE NORTH 30.0 FT. OF THE WEST 1408.0 FT. OF THE EAST 1441.0 FT. OF THE SE¼ OF SEC. 9-T11N.-R5E. OF THE 6TH P.M.

LEGAL DESCRIPTION

A part of the Southeast Quarter of Section 9, Township 11 North, Range 5 East of the 6th P.M., Lancaster County, Nebraska described as follows: Beginning at the northeast corner of said Southeast Quarter; thence southerly along the east line of said Southeast Quarter, a distance of 612.22 feet; thence westerly deflecting 90°00' right, a distance of 1,187.00 feet; thence southerly deflecting 90°00' left, a distance of 662.07 feet; thence westerly deflecting 89°30' right, a distance of 254.00 feet; thence northerly deflecting 90°30' right, a distance of 1,271.05 feet to the north line of said Southeast Quarter; thence easterly along said north line, a distance of 1,441.00 feet to the Point of Beginning, containing 24.02 acres, more or less, and including road right of way.

SURVEYOR'S CERTIFICATE

I hereby certify that, to the best of my ability, I have accurately surveyed the property in the above plat. All dimensions are in feet and decimals of a foot and are chord measurements unless otherwise noted.

NEBRASKA REGISTERED LS-246 LAND SURVEYOR PAUL E. KASL

PAUL E. KASL
SURVEYOR L.S.–246
3101 LOVELAND DRIVE
LINCOLN, NEBRASKA 68502


Signed this 12TH day of Jan. 1992

Name Paul E. Kasl

LAND SURVEYOR'S SEAL

LOCATION SURVEY

12701 NW. 98TH ST.
DON KINLEY



Paul E. Kasl

Jan. 4, 1992

NEBRASKA REGISTERED LS-246 LAND SURVEYOR PAUL E. KASL

SURVEY RECORD

Farm 3941

LANCASTER COUNTY, NEBRASKA


Survey of PART OF SE¼ (58.88± Ac.)

SE¼ Section 9 T. 11 N., R. 5 E.

of 6th P.M.

County Survey No.

Date SEPT. 23 - OCT. 9 19 89 Weather



SURVEYOR'S CERTIFICATE

I hereby certify that, to the best of my ability, I have accurately surveyed the property in the above plat. All dimensions are in feet and decimals of a foot and are chord measurements unless otherwise noted.

NEBRASKA REGISTERED LS-246 LAND SURVEYOR PAUL E. KASL

LAND SURVEYOR'S SEAL

PAUL E. KASL
SURVEYOR L.S.—246
3101 LOVELAND DRIVE
LINCOLN, NEBRASKA 68502

Signed this 10TH day of OCT. 19 89

Name Paul E. Kasl

LINCOLN-LANCASTER COUNTY HEALTH DEPARTMENT

2200 St Marys Avenue Phone (402) 471-7800 Lincoln, Nebraska 68502

REAL ESTATE TRANSFER / LOAN APPROVAL

This form must be completed and returned to request a real estate transfer inspection.

MAKE CHECKS PAYABLE TO: Lincoln-Lancaster County Health Department.

☒ Evaluation of the Individual Water System Date: 2-6-92.

☒ Evaluation of the Sewage Disposal System ☐ Enclosed is $150.00

Legal Description of Property: TWP. 11N; RANGE 5E; SECTION 9; BLOCK ___

LOT ___; ADDITION See attached; Street Address 12701 N.W. 98th, Malcolm.

Directions to Property ½ North junction of NW 98th & W. Waverly Rd. West Side of Road

Location of Well See attached survey Tap Location: Inside ☐ Outside ☐

Location of Sewage System See attached survey Year Installed 1990 Oct

	NAME	ADDRESS	PHONE
Present Owner:	Donald O. & Debra J. Kinley	12701 N.W. 98th Malcolm	434 4655-w
Tenant/Buyer:			
Return to:	Kathy Mauer First Comm. Mtg	1230 "O" Street Lincoln 68508	434-4669

NOTE: Allow two weeks for processing. Incomplete information will delay processing.

Signature of Applicant Donald O. Kinley Address 12701 N.W. 98th St. Malcolm Ne. 68402

==========

HEALTH DEPARTMENT USE ONLY

Date Received FEBRUARY 10, 1992 Received $150.00 Check ☒ Cash ☐

PRELIMINARY STATUS--DATE 2-10-92

WATER SYSTEM:	Approved	Disapproved	SEWAGE SYSTEM:		SITE VISIT:
Construction	☒	☐	Approved:	☐	Date 2-10-92 by ___
Bacteria	☒	☐	Provisional:	☐	Date ___ by ___
Nitrate	☒	☐	Disapproved:	☒	Date ___ by ___

Comments: ___

See Attached Letter ☐

FINAL STATUS

	WATER SYSTEM:	SEWAGE DISPOSAL SYSTEM:	
	Approved: ☒	Approved: ☒	Provisional Approval: ☐

APPROVED BY Ron Magnuson DATE 2-12-92

Approval or disapproval is based on written standards for construction, location and water quality. Inspection is based on visible construction and operation at the time of inspection. Approval or provisional approval does not imply or express a guarantee of system operation. WELLS - Nebraska Safe Drinking Water Act,
- Standards for A Private Well in Nebraska

FG.4120 INDIVIDUAL SEWAGE SYSTEMS - County Resolution #2832